

11.8555

30216

Missouri La Forge
Farms Project
Unit 32

Not used



Another bad example of water system
installation. Note: Lamp cord to motor;
unprotected pipe up wall; waste water
in open ditch, without proper drainage.
Taken by: Jefferson B. Rodgers. 1941
inadequate protection of water system.

